



大成環境科技拓展有限公司  
Environmental Pioneers and Solutions Limited

Water Quality Monitoring Data Sheet

Location					
Monitoring Location		M1		M2	
Date		8/9/2008			
Weather		Sunny			
River Condition		Normal		Normal	
Tide Mode		ebb			
Start Time (hh:mm)		1100		1115	
Water Depth (m)		< 1		< 1	
pH Value		7.33		7.14	
Temperture (oC)		28.4		29.7	
Salinity (ppt)		0.1		0	
Turbidity (NTU)		2.5	2.6	< 0.1	0.1
Sample ID		M1	M1D	M2	M2D
DO (mg/l)		5.82	6.13	5.4	5.52
DO Saturation (%)		83	88	90	94
Observed Construction Activities	< 100m from location				
	> 100m from location	Site Clearance works were found being carried out in site of PNH			
Other Observation					

Name & Designation

Signature

Date

Recorded by: Hugo Lee \_\_\_\_\_ 8/9/2008

Checked by: Jimmy Cheng \_\_\_\_\_ 8/9/2008



大成環境科技拓展有限公司  
Environmental Pioneers and Solutions Limited

Water Quality Monitoring Data Sheet

Location					
Monitoring Location		M3		M4	
Date		8/9/2008			
Weather		Sunny			
River Condition		Normal		Normal	
Tide Mode		ebb			
Start Time (hh:mm)		1400		1045	
Water Depth (m)		< 1		< 1	
pH Value		6.98		7.13	
Temperture (oC)		33.3		29.8	
Salinity (ppt)		3		2.9	
Turbidity (NTU)		4.8	4.7	6.3	6.6
Sample ID		M3	M3D	M4	M4D
DO (mg/l)		7.57	7.58	6.45	6.43
DO Saturation (%)		110	107	94	95
Observed Construction Activities	< 100m from location				
	> 100m from location				
Other Observation					

Name & Designation

Signature

Date

Recorded by: Hugo Lee \_\_\_\_\_ 8/9/2008

Checked by: Jimmy Cheng \_\_\_\_\_ 8/9/2008



大成環境科技拓展有限公司  
Environmental Pioneers and Solutions Limited

Water Quality Monitoring Data Sheet

Location					
Monitoring Location		C1		C2	
Date		8/9/2008			
Weather		Sunny			
River Condition		Normal		Normal	
Tide Mode		ebb			
Start Time (hh:mm)		1145		1210	
Water Depth (m)		< 1		< 1	
pH Value		6.85		6.8	
Temperture (oC)		27		30	
Salinity (ppt)		0		0	
Turbidity (NTU)		1.7	1.6	0.5	0.5
Sample ID		C1	C1D	C2	C2D
DO (mg/l)		5.12	5.13	6.31	6.32
DO Saturation (%)		78	79	84	86
Observed Construction Activities	< 100m from location	Site Clearance was being carried out in the site of PNH			
	> 100m from location				
Other Observation					

Name & Designation

Signature

Date

Recorded by: Hugo Lee \_\_\_\_\_ 8/9/2008

Checked by: Jimmy Cheng \_\_\_\_\_ 8/9/2008



大成環境科技拓展有限公司  
Environmental Pioneers and Solutions Limited

Water Quality Monitoring Data Sheet

Location			
Monitoring Location	C3		
Date	8/9/2008		
Weather	Sunny		
River Condition	Normal		
Tide Mode	ebb		
Start Time (hh:mm)	1230		
Water Depth (m)	< 1		
pH Value	6.36		
Temperture (oC)	27.7		
Salinity (ppt)	0		
Turbidity (NTU)	1.7	1.6	
Sample ID	C3	C3D	
DO (mg/l)	3.52	3.45	
DO Saturation (%)	46	41	
Observed Construction Activities	< 100m from location		
	> 100m from location		
Other Observation			

Name & Designation

Signature

Date

Recorded by: Hugo Lee \_\_\_\_\_ 8/9/2008

Checked by: Jimmy Cheng \_\_\_\_\_ 8/9/2008