



大成環境科技拓展有限公司

Environmental Pioneers and Solutions Limited

Water Quality Monitoring Data Sheet

Location					
Monitoring Location		M1		M2	
Date		12/9/2008			
Weather		Sunny			
River Condition		Normal		Normal	
Tide Mode		ebb			
Start Time	(hh:mm)	1110		1120	
Water Depth	(m)	< 1		< 1	
pH Value		7.21		7.14	
Temperture	(oC)	28.5		29.2	
Salinity	(ppt)	1.7		0.6	
Turbidity	(NTU)	0.8	0.7	< 0.1	< 0.1
Sample ID		M1	M1D	M2	M2D
DO	(mg/l)	8.81	8.8	7.92	7.94
DO Saturation	(%)	121	120	105	108
Observed Construction Activities	< 100m from location				
	> 100m from location	Site Clearance works were found being carried out in site of PNH			
Other Observation					

Name & Designation

Signature

Date

Recorded by: Hugo Lee _____ 12/9/2008

Checked by: Jimmy Cheng _____ 12/9/2008



大成環境科技拓展有限公司
Environmental Pioneers and Solutions Limited

Water Quality Monitoring Data Sheet

Location					
Monitoring Location		M3		M4	
Date		12/9/2008			
Weather		Sunny			
River Condition		Normal		Normal	
Tide Mode		ebb			
Start Time (hh:mm)		1230		1055	
Water Depth (m)		< 1		< 1	
pH Value		6.89		7.39	
Temperture (oC)		32.5		29.6	
Salinity (ppt)		12.2		12.2	
Turbidity (NTU)		5.3	5.2	1	0.9
Sample ID		M3	M3D	M4	M4D
DO (mg/l)		8.02	8.04	6.89	6.88
DO Saturation (%)		110	107	94	95
Observed Construction Activities	< 100m from location				
	> 100m from location				
Other Observation					

Name & Designation

Signature

Date

Recorded by: Hugo Lee _____ 12/9/2008

Checked by: Jimmy Cheng _____ 12/9/2008



大成環境科技拓展有限公司
Environmental Pioneers and Solutions Limited

Water Quality Monitoring Data Sheet

Location					
Monitoring Location		C1		C2	
Date		12/9/2008			
Weather		Sunny			
River Condition		Normal		Normal	
Tide Mode		ebb			
Start Time (hh:mm)		1110		1045	
Water Depth (m)		< 1		< 1	
pH Value		6.63		6.63	
Temperture (oC)		27.8		29.5	
Salinity (ppt)		0		0	
Turbidity (NTU)		2.4	2.4	3	3.1
Sample ID		C1	C1D	C2	C2D
DO (mg/l)		7.39	7.39	8.4	8.4
DO Saturation (%)		104	103	112	114
Observed Construction Activities	< 100m from location	Site Clearance was being carried out in the site of PNH			
	> 100m from location				
Other Observation					

Name & Designation

Signature

Date

Recorded by: Hugo Lee _____ 12/9/2008

Checked by: Jimmy Cheng _____ 12/9/2008



大成環境科技拓展有限公司
Environmental Pioneers and Solutions Limited

Water Quality Monitoring Data Sheet

Location			
Monitoring Location	C3		
Date	12/9/2008		
Weather	Sunny		
River Condition	Normal		
Tide Mode	ebb		
Start Time (hh:mm)	1130		
Water Depth (m)	< 1		
pH Value	6.53		
Temperture (oC)	27.9		
Salinity (ppt)	0		
Turbidity (NTU)	3.4	3.4	
Sample ID	C3	C3D	
DO (mg/l)	3.44	3.41	
DO Saturation (%)	40	38	
Observed Construction Activities	< 100m from location		
	> 100m from location		
Other Observation	Oil Layers were found on the water surface of monitoring point C3		

Name & Designation

Signature

Date

Recorded by: Hugo Lee _____ 12/9/2008

Checked by: Jimmy Cheng _____ 12/9/2008