



# 大成環境科技拓展有限公司

## Environmental Pioneers and Solutions Limited

### Water Quality Monitoring Data Sheet

Location					
Monitoring Location		M1		M2	
Date		17/9/2008			
Weather		Sunny			
River Condition		Normal		Normal	
Tide Mode		ebb			
Start Time	(hh:mm)	1515		1400	
Water Depth	(m)	< 1		< 1	
pH Value		7.18		7.3	
Temperture	(oC)	30.2		31.2	
Salinity	(ppt)	1.7		2.2	
Turbidity	(NTU)	1.2	1.2	2.9	2.8
Sample ID		M1	M1D	M2	M2D
DO	(mg/l)	8.54	8.55	8.25	8.26
DO Saturation	(%)	114	116	109	109
Observed Construction Activities	< 100m from location				
	> 100m from location	Site Clearance works were found being carried out in site of PNH			
Other Observation					

Name & Designation

Signature

Date

Recorded by: Hugo Lee \_\_\_\_\_ 17/9/2008

Checked by: Jimmy Cheng \_\_\_\_\_ 17/9/2008



大成環境科技拓展有限公司  
Environmental Pioneers and Solutions Limited

Water Quality Monitoring Data Sheet

Location					
Monitoring Location		M3		M4	
Date		17/9/2008			
Weather		Sunny			
River Condition		Normal		Normal	
Tide Mode		ebb			
Start Time	(hh:mm)	1530		1600	
Water Depth	(m)	< 1		< 1	
pH Value		7.38		7.98	
Temperture	(oC)	33		32.7	
Salinity	(ppt)	14.2		11.2	
Turbidity	(NTU)	3.7	3.8	2.4	2.4
Sample ID		M3	M3D	M4	M4D
DO	(mg/l)	8.57	8.53	8.56	8.56
DO Saturation	(%)	118	118	112	112
Observed Construction Activities	< 100m from location				
	> 100m from location				
Other Observation					

Name & Designation

Signature

Date

Recorded by: Hugo Lee \_\_\_\_\_ 17/9/2008

Checked by: Jimmy Cheng \_\_\_\_\_ 17/9/2008



# 大成環境科技拓展有限公司

## Environmental Pioneers and Solutions Limited

### Water Quality Monitoring Data Sheet

Location						
Monitoring Location		C1		C2		
Date		17/9/2008				
Weather		Rainy				
River Condition		Normal		Normal		
Tide Mode		ebb				
Start Time	(hh:mm)	1445		1425		
Water Depth	(m)	< 1		< 1		
pH Value		6.6		6.63		
Temperture	(oC)	29.3		30.7		
Salinity	(ppt)	0		0		
Turbidity	(NTU)	< 0.1	< 0.1	0.2	0.3	
Sample ID		C1	C1D	C2	C2D	
DO		(mg/l)	7.63	7.64	8.36	8.37
DO Saturation		(%)	104	103	117	119
Observed Construction Activities	< 100m from location	Site Clearance was being carried out in the site of PNH				
	> 100m from location					
Other Observation						

Name & Designation

Signature

Date

Recorded by: Hugo Lee \_\_\_\_\_ 17/9/2008

Checked by: Jimmy Cheng \_\_\_\_\_ 17/9/2008



大成環境科技拓展有限公司  
Environmental Pioneers and Solutions Limited

Water Quality Monitoring Data Sheet

Location			
Monitoring Location	C3		
Date	17/9/2008		
Weather	Sunny		
River Condition	Normal		
Tide Mode	ebb		
Start Time (hh:mm)	1410		
Water Depth (m)	< 1		
pH Value	6.42		
Temperture (oC)	28.3		
Salinity (ppt)	0		
Turbidity (NTU)	2	2.1	
Sample ID	C3	C3D	
DO (mg/l)	3.24	3.23	
DO Saturation (%)	46	42	
Observed Construction Activities	< 100m from location		
	> 100m from location		
Other Observation			

Name & Designation

Signature

Date

Recorded by: Hugo Lee \_\_\_\_\_ 17/9/2008

Checked by: Jimmy Cheng \_\_\_\_\_ 17/9/2008