



大成環境科技拓展有限公司
Environmental Pioneers and Solutions Limited

Water Quality Monitoring Data Sheet

Location					
Monitoring Location		M1		M2	
Date		19/9/2008			
Weather		Sunny			
River Condition		Normal		Normal	
Tide Mode		ebb			
Start Time (hh:mm)		1438		1435	
Water Depth (m)		< 1		< 1	
pH Value		6.99		7.57	
Temperture (oC)		28.3		29.1	
Salinity (ppt)		0.2		0	
Turbidity (NTU)		4.7	4.7	< 0.1	< 0.1
Sample ID		M1	M1D	M2	M2D
DO (mg/l)		8.26	8.3	8.03	8.04
DO Saturation (%)		109	109	109	109
Observed Construction Activities	< 100m from location				
	> 100m from location	Site Clearance works were found being carried out in site of PNH			
Other Observation					

Name & Designation

Signature

Date

Recorded by: Hugo Lee _____ 19/9/2008

Checked by: Jimmy Cheng _____ 19/9/2008



大成環境科技拓展有限公司
Environmental Pioneers and Solutions Limited

Water Quality Monitoring Data Sheet

Location					
Monitoring Location		M3		M4	
Date		19/9/2008			
Weather		Sunny			
River Condition		Normal		Normal	
Tide Mode		ebb			
Start Time (hh:mm)		1430		1415	
Water Depth (m)		< 1		< 1	
pH Value		7.15		7.45	
Temperture (oC)		30		29.6	
Salinity (ppt)		4.1		6.7	
Turbidity (NTU)		7	7.3	7.5	7.5
Sample ID		M3	M3D	M4	M4D
DO (mg/l)		7.37	7.4	7.83	7.82
DO Saturation (%)		108	107	105	106
Observed Construction Activities	< 100m from location				
	> 100m from location				
Other Observation					

Name & Designation

Signature

Date

Recorded by: Hugo Lee _____ 19/9/2008

Checked by: Jimmy Cheng _____ 19/9/2008



大成環境科技拓展有限公司

Environmental Pioneers and Solutions Limited

Water Quality Monitoring Data Sheet

Location					
Monitoring Location		C1		C2	
Date		19/9/2008			
Weather		Rainy			
River Condition		Normal		Normal	
Tide Mode		ebb			
Start Time	(hh:mm)	1455		1505	
Water Depth	(m)	< 1		< 1	
pH Value		6.92		6.81	
Temperture	(oC)	28		28.3	
Salinity	(ppt)	0		0	
Turbidity	(NTU)	< 0.1	< 0.1	0.3	0.1
Sample ID		C1	C1D	C2	C2D
DO	(mg/l)	7.55	7.54	7.89	7.93
DO Saturation	(%)	104	103	107	108
Observed Construction Activities	< 100m from location	Site Clearance was being carried out in the site of PNH			
	> 100m from location				
Other Observation					

Name & Designation

Signature

Date

Recorded by: Hugo Lee _____ 19/9/2008

Checked by: Jimmy Cheng _____ 19/9/2008



大成環境科技拓展有限公司
Environmental Pioneers and Solutions Limited

Water Quality Monitoring Data Sheet

Location			
Monitoring Location	C3		
Date	19/9/2008		
Weather	Sunny		
River Condition	Normal		
Tide Mode	ebb		
Start Time (hh:mm)	1520		
Water Depth (m)	< 1		
pH Value	6.39		
Temperture (oC)	27.4		
Salinity (ppt)	0		
Turbidity (NTU)	2.1	2.2	
Sample ID	C3	C3D	
DO (mg/l)	3.49	3.45	
DO Saturation (%)	42	42	
Observed Construction Activities	< 100m from location		
	> 100m from location		
Other Observation			

Name & Designation

Signature

Date

Recorded by: Hugo Lee _____ 19/9/2008

Checked by: Jimmy Cheng _____ 19/9/2008