



大成環境科技拓展有限公司

Environmental Pioneers and Solutions Limited

Water Quality Monitoring Data Sheet

Location					
Monitoring Location		M1		M2	
Date		22/9/2008			
Weather		Sunny			
River Condition		Normal		Normal	
Tide Mode		ebb			
Start Time	(hh:mm)	1155		1145	
Water Depth	(m)	< 1		< 1	
pH Value		7.33		7.54	
Temperture	(oC)	30.2		30.6	
Salinity	(ppt)	0.7		0.5	
Turbidity	(NTU)	10.7	10.6	0	0
Sample ID		M1	M1D	M2	M2D
DO	(mg/l)	8.64	8.66	7.96	8.04
DO Saturation	(%)	117	117	110	113
Observed Construction Activities	< 100m from location				
	> 100m from location	Site Clearance works were found being carried out in site of PNH			
Other Observation					

Name & Designation

Signature

Date

Recorded by: Hugo Lee _____ 22/9/2008

Checked by: Jimmy Cheng _____ 22/9/2008



大成環境科技拓展有限公司
Environmental Pioneers and Solutions Limited

Water Quality Monitoring Data Sheet

Location					
Monitoring Location		M3		M4	
Date		22/9/2008			
Weather		Sunny			
River Condition		Normal		Normal	
Tide Mode		ebb			
Start Time (hh:mm)		1140		1130	
Water Depth (m)		< 1		< 1	
pH Value		6.91		7.5	
Temperture (oC)		31.8		32.4	
Salinity (ppt)		9.9		6.8	
Turbidity (NTU)		14.2	14.1	9.1	9.1
Sample ID		M3	M3D	M4	M4D
DO (mg/l)		8.8	8.81	8.01	8.04
DO Saturation (%)		126	126	112	113
Observed Construction Activities	< 100m from location				
	> 100m from location				
Other Observation					

Name & Designation

Signature

Date

Recorded by: Hugo Lee _____ 22/9/2008

Checked by: Jimmy Cheng _____ 22/9/2008



大成環境科技拓展有限公司
Environmental Pioneers and Solutions Limited

Water Quality Monitoring Data Sheet

Location					
Monitoring Location		C1		C2	
Date		22/9/2008			
Weather		Sunny			
River Condition		Normal		Normal	
Tide Mode		ebb			
Start Time (hh:mm)		1440		1425	
Water Depth (m)		< 1		< 1	
pH Value		6.64		6.57	
Temperture (oC)		30		30.9	
Salinity (ppt)		0		0	
Turbidity (NTU)		0	0	0	0
Sample ID		C1	C1D	C2	C2D
DO (mg/l)		7.55	7.55	8.47	8.47
DO Saturation (%)		101	101	114	114
Observed Construction Activities	< 100m from location	Site Clearance was being carried out in the site of PNH			
	> 100m from location				
Other Observation					

Name & Designation

Signature

Date

Recorded by: Hugo Lee _____ 22/9/2008

Checked by: Jimmy Cheng _____ 22/9/2008



大成環境科技拓展有限公司
Environmental Pioneers and Solutions Limited

Water Quality Monitoring Data Sheet

Location			
Monitoring Location	C3		
Date	22/9/2008		
Weather	Sunny		
River Condition	Normal		
Tide Mode	ebb		
Start Time (hh:mm)	1415		
Water Depth (m)	< 1		
pH Value	6.59		
Temperture (oC)	30.1		
Salinity (ppt)	0.1		
Turbidity (NTU)	4.2	4.2	
Sample ID	C3	C3D	
DO (mg/l)	3.16	3.14	
DO Saturation (%)	41	41	
Observed Construction Activities	< 100m from location		
	> 100m from location		
Other Observation			

Name & Designation

Signature

Date

Recorded by: Hugo Lee _____ 22/9/2008

Checked by: Jimmy Cheng _____ 22/9/2008