



大成環境科技拓展有限公司

Environmental Pioneers and Solutions Limited

Water Quality Monitoring Data Sheet

Location					
Monitoring Location		M1		M2	
Date		26/9/2008			
Weather		Sunny			
River Condition		Normal		Normal	
Tide Mode		ebb			
Start Time	(hh:mm)	1206		1206	
Water Depth	(m)	< 1		< 1	
pH Value		6.74		7.05	
Temperture	(oC)	28.6		29.5	
Salinity	(ppt)	0.3		0.1	
Turbidity	(NTU)	2.7	2.7	0	0
Sample ID		M1	M1D	M2	M2D
DO	(mg/l)	6.96	6.98	6.53	6.52
DO Saturation	(%)	90	91	87	87
Observed Construction Activities	< 100m from location				
	> 100m from location	Site Clearance works were found being carried out in site of PNH			
Other Observation					

Name & Designation

Signature

Date

Recorded by: Hugo Lee _____ 26/9/2008

Checked by: Jimmy Cheng _____ 26/9/2008



大成環境科技拓展有限公司
Environmental Pioneers and Solutions Limited

Water Quality Monitoring Data Sheet

Location					
Monitoring Location		M3		M4	
Date		26/9/2008			
Weather		Sunny			
River Condition		Normal		Normal	
Tide Mode		ebb			
Start Time (hh:mm)		1155		1140	
Water Depth (m)		< 1		< 1	
pH Value		6.79		6.81	
Temperture (oC)		30.9		30.1	
Salinity (ppt)		6.6		4.4	
Turbidity (NTU)		5.8	5.8	3.5	3.5
Sample ID		M3	M3D	M4	M4D
DO (mg/l)		5.97	5.96	6.05	6.04
DO Saturation (%)		83	83	83	83
Observed Construction Activities	< 100m from location				
	> 100m from location				
Other Observation					

Name & Designation

Signature

Date

Recorded by: Hugo Lee _____ 26/9/2008

Checked by: Jimmy Cheng _____ 26/9/2008



大成環境科技拓展有限公司

Environmental Pioneers and Solutions Limited

Water Quality Monitoring Data Sheet

Location					
Monitoring Location		C1		C2	
Date		26/9/2008			
Weather		Sunny			
River Condition		Normal		Normal	
Tide Mode		ebb			
Start Time	(hh:mm)	1105		1045	
Water Depth	(m)	< 1		< 1	
pH Value		6.25		6.38	
Temperture	(oC)	27.4		27.9	
Salinity	(ppt)	0		0	
Turbidity	(NTU)	0.3	0.4	0	0
Sample ID		C1	C1D	C2	C2D
DO	(mg/l)	7.02	7.01	7.09	7.08
DO Saturation	(%)	90	89	92	91
Observed Construction Activities	< 100m from location	Site Clearance works were found being carried out in site of PNH			
	> 100m from location				
Other Observation					

Name & Designation

Signature

Date

Recorded by: Hugo Lee _____ 26/9/2008

Checked by: Jimmy Cheng _____ 26/9/2008



大成環境科技拓展有限公司
Environmental Pioneers and Solutions Limited

Water Quality Monitoring Data Sheet

Location			
Monitoring Location	C3		
Date	26/9/2008		
Weather	Sunny		
River Condition	Normal		
Tide Mode	ebb		
Start Time (hh:mm)	1030		
Water Depth (m)	< 1		
pH Value	6.25		
Temperture (oC)	26.9		
Salinity (ppt)	0		
Turbidity (NTU)	0	0	
Sample ID	C3	C3D	
DO (mg/l)	3.68	3.7	
DO Saturation (%)	45	45	
Observed Construction Activities	< 100m from location		
	> 100m from location		
Other Observation			

Name & Designation

Signature

Date

Recorded by: Hugo Lee _____ 26/9/2008

Checked by: Jimmy Cheng _____ 26/9/2008