



大成環境科技拓展有限公司
Environmental Pioneers and Solutions Limited

Construction Noise Monitoring Data Sheet

Monitoring Location		N1	N2
Description of Location		Façade	Façade
Date of Monitoring		08/11/3	
Measurement Start Time (hhmm)		1520	1445
Measurement Time Length (mins.)		30 mins	
Noise Meter Model/ Identification		SVAN 949	
Calibrator Model/ Identification		SVAN SV 30A	
Wind Speed (m/s)		0.3	0.2
Measurement Results	L90 (dB(A))	48.0	40.3
	L10 (dB(A))	51.8	55.7
	Leq (dB(A))	51.2	6.6
Weather condition:		Sunny	
Major Construction Noise Source(s) During Monitoring		no construction works are being carried out during measurement.	no construction works are being carried out during measurement.
Other Noise Source(s) During Monitoring		Public Noise	1. Public Noise 2. Traffic Noise (Bicycle)
Remarks			


Name & Designation

Signature

Date:

Prepared by:

Jimmy Cheng



08/11/3



大成環境科技拓展有限公司
Environmental Pioneers and Solutions Limited

Construction Noise Monitoring Data Sheet

Monitoring Location		N3	N4
Description of Location		Freefield	Façade
Date of Monitoring		08/11/3	
Measurement Start Time (hhmm)		1300	1335
Measurement Time Length (mins.)		30 mins	
Noise Meter Model/ Identification		SVAN 949	
Calibrator Model/ Identification		SVAN SV 30A	
Wind Speed (m/s)		1.1	1.6
Measurement Results	L90 (dB(A))	38.6	52.7
	L10 (dB(A))	50.8	61.5
	Leq (dB(A))	51.4	62.8
Weather condition:		Sunny	
Major Construction Noise Source(s) During Monitoring		no construction works are being carried out during measurement.	1.Excavator Noise 2.Welding Noise 3.Power Generator 4.Concrete Truck unload concrete
Other Noise Source(s) During Monitoring			
Remarks			

Name & Designation

Signature

Date:

Prepared by:

Jimmy Cheng

08/11/3