

**Environmental Pioneers & Solutions Limited**  
**Water Quality Monitoring - Summary of On-site measurement results**

Date of Sampling: 2008/11/12      Sunny

Monitoring Location	M1			M2			M3			M4			C1			C2			C3		
Time (hhmm)	1340			1350			1400			1425			1310			1320			1415		
Tide Mode	mid-ebb			mid-ebb			mid-ebb			mid-ebb			mid-ebb			mid-ebb			mid-ebb		
River Condition	normal			normal			normal			normal			normal			normal			normal		
Water Depth (m)	< 1			< 1			< 1			0.8			< 1			0.8			< 1		
pH value	6.82			7.18			7.30			7.93			6.67			7.08			7.13		
Temperature (oC)	21.9			23.0			25.0			24.2			19.1			19.8			22.5		
Salinity (ppt)	2.9			1.3			17.6			23.1			0.0			0.0			1.1		
Turbidity (NTU)	3.5	3.5	Average	3.0	3.0	Average	8.6	8.6	Average	13.2	13.2	Average	1.9	1.9	Average	1.0	1.0	Average	5.1	5.1	Average
			3.5			3.0			8.6			13.2			1.9			1.0			5.1
DO (mg/l)	9.30	9.30	Average	8.42	8.42	Average	8.04	8.04	Average	6.26	6.26	Average	8.57	8.57	Average	8.48	8.48	Average	4.67	4.67	Average
			9.30			8.42			8.04			6.26			8.57			8.48			4.67
DO Saturation (%)	111	111	Average	99	99	Average	90	90	Average	85	85	Average	100	100	Average	99	99	Average	55	55	Average
			111			99			90			85			100			99			55

Name  
Prepared By: Jimmy Cheng

Signature  


Date  
2008/11/12

remark or observation: \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_