

Environmental Pioneers & Solutions Limited
Water Quality Monitoring - Summary of On-site measurement results

Date of Sampling: 2008/11/14 Sunny

Monitoring Location	M1			M2			M3			M4			C1			C2			C3		
Time (hhmm)	1445			1335			1345			1315			1410			1420			1435		
Tide Mode	mid-ebb			mid-ebb			mid-ebb			mid-ebb			mid-ebb			mid-ebb			mid-ebb		
River Condition	normal			normal			normal			normal			normal			normal			normal		
Water Depth (m)	< 1			< 1			< 1			< 1			< 1			< 1			< 1		
pH value	7.72			7.31			7.43			7.97			7.24			6.70			6.79		
Temperature (oC)	24.9			25.3			27.2			25.5			22.5			23.3			24.5		
Salinity (ppt)	2.1			1.4			15.6			20.9			0.0			0.0			3.0		
Turbidity (NTU)	11.9	11.9	Average	3.6	3.6	Average	12.0	12.0	Average	8.0	8.0	Average	5.0	5.0	Average	3.0	3.0	Average	8.3	8.3	Average
			11.9			3.6			12.0			8.0			5.0			3.0			8.3
DO (mg/l)	9.62	9.62	Average	8.14	8.14	Average	8.43	8.43	Average	7.03	7.03	Average	8.24	8.24	Average	7.77	7.77	Average	3.72	3.72	Average
			9.62			8.14			8.43			7.03			8.24			7.77			3.72
DO Saturation (%)	117	117	Average	100	100	Average	105	105	Average	90	90	Average	101	101	Average	96	96	Average	44	44	Average
			117			100			105			90			101			96			44

Name
Prepared By: Jimmy Cheng

Signature


Date
2008/11/14

remark or observation: _____

