

**Environmental Pioneers & Solutions Limited**  
**Water Quality Monitoring - Summary of On-site measurement results**

Date of Sampling: 2008/11/24      Sunny

Monitoring Location	M1			M2			M3			M4			C1			C2			C3		
Time (hhmm)	1100			1110			1120			1140			1420			1435			1455		
Tide Mode	mid-ebb			mid-ebb			mid-ebb			mid-ebb			mid-ebb			mid-ebb			mid-ebb		
River Condition	normal			normal			normal			normal			normal			normal			normal		
Water Depth (m)	< 1			< 1			< 1			0.7			< 1			<1			< 1		
pH value	7.49			7.20			6.81			7.75			7.17			7.07			7.02		
Temperature (oC)	21.7			21.8			22.8			23.7			21.7			22.5			22.6		
Salinity (ppt)	1.0			0.4			6.6			11.3			0.2			0.0			0.5		
Turbidity (NTU)	4.3	4.3	Average	1.1	1.1	Average	3.3	3.3	Average	6.0	6.0	Average	1.3	1.3	Average	1.6	1.6	Average	7.6	7.6	Average
			4.3			1.1			3.3			6.0			1.3			1.6			7.6
DO (mg/l)	8.87	8.87	Average	8.43	8.43	Average	8.82	8.82	Average	7.78	7.80	Average	8.01	8.01	Average	8.33	8.33	Average	3.35	3.35	Average
			8.87			8.43			8.82			7.79			8.01			8.33			3.35
DO Saturation (%)	102	102	Average	96	96	Average	102	102	Average	89	89	Average	94	94	Average	96	96	Average	39	39	Average
			102			96			102			89			94			96			39

Name  
Prepared By: Jimmy Cheng

Signature  


Date  
2008/11/24

remark or observation: \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_